

1. Original and/or subsequent record used to evaluate the comer position.

2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.

3. Description of monument and accessories set to perpetuate the corner position.

4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories,

5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner <u>Section Corner to Sections 7,8,17 and 18</u> T. <u>25 N.</u> R. 30 W. P.M.M. <u>LINCOLN</u> County

RECORD:

S. Frank Walters and Carl Dyson, U.S. Deputy Surveyors, 1916

80.00 Set a Limestone, 16x10x4 ins., 10 ins. in the ground, for cor. Of secs. 7, 8, 17, and 18, marked with 5 notches on the E. and 4 notches on the S. edges, and raise a mound of stone, 2 ft. 1 ½ ft. high, E. of the cor.

FOUND:

Found a stone 4" x 12" firmly set on S. side of a ridge, with 5 notches on the E., and 4 notches on the S. A stone mound, 36" x 12" bears East, 3 feet.

TO PERPETUATE:

At the found stone position, set a 2-1/2" x 30" aluminum pipe, with a 3-1/4" aluminum cap, 8" in the ground and marked as shown below. Raise a 48" x 24" mound of stone to cap, placed found corner stone at bottom of mound and incorporate the stone mound to the east into the new mound.

From which new trees:

A lodgepole pine, 12"in diam., bears N.14°E., 39.3', blazed and scribed "T25N R30W S8 BT". A hemlock, 7" in diam., bears S.06°W., 21.3' blazed and scribed "T25N R30W S18 BT". A hemlock, 7" in diam., bears N.23°W., 20.5' blazed and scribed "T25N R30W S7 BT".

No available trees in section 17.

Corner Number 4 of Mineral Survey Number 6191 (Sentinel), bears S.03°12'33"E., 332.01', monumented with a 5/8" x 24" rebar, with a USFS 3-1/4" aluminum cap. (see Certified Corner Recordation form T.25N. R.30W. J-K/5)

Place a "Land Survey Monument" (54-9), and a "Bearing Tree" (54-3) sign on the bearing trees. Painted all blazes red, and a 6" red band above the "Bearing Tree" signs. Placed 6' steel posts near the corner, with "Land Survey Marker" (54-9) decals.

Note: this is a corner re-monumentation only, and it is not tied to any other PLSS corner.

See Certificate of Survey, recorded in Lincoln County	
THEMICA K IZ"LODGE POLE PINE CONTROL OF THE PI	CERTIFICATION I, Matt Jacobson certify the information shown begin is true and correct. Signature Ground Pagey Chief I, R.A. Ainsworth certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner
SKETCH OF CORNER	Employer: Professional Consultants, Inc.
Office of Clerk and Recorder, County of And This "corner record" was filed for record on was noted on the cross-index plat and is assigned page No. 10492, in book No. County Official	