## CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

Never Established

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: Sept. 1980...


DIAGRAM OF CORNER:

Set a 5/8" Capped rebar, MDL 4232-S, for the SE 1/16th Cor. of Sec. 5, T26N, R27W, P.M.M., From Which:

A 14" Spruce bears N41°-22'E, 8.80 ft. mkd. SE 1/16, S5, 8.T. A 12" Spruce bears S59°-00'E, 19.90 ft., mkd. SE 1/16, S5, 8.T.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.

(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)



Surveyor's Seal



KENETH KERN certify that the information shown herein is true and correct.

Kennth Kerw Signature of Ground Party Chief

, MELVIN D. LAUTEREN certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

Signature of Surveyor

Corner recorded on the sheet SEY16th S-5, 726N, R27W

4232-S Registration Number

Office of Clerk and Recorder, County of Juncoln This "corner record" was filed for record on the 25th day of Mouemble 19.80, was noted on the cross-index plat and is assigned page No....., in book No. 226 Cross Index No. 8-D T. 26N R 27W Form 125—7887