## **CERTIFIED LAND CORNER RECORDATION**

(REFERENCE FSM 7153.53)

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

No original record

## DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: 11/80

Set aluminum post 27" long,  $2\frac{1}{4}$ " dia. with aluminum cap 20" in ground, from which:

A Spruce 14" dia. bears N21°E 25.3 ft. mkd. W 1/16 BT. A Fir 10" dia. bears S07°W 7.5 ft. mkd. W 1/16 BT.

Sketch of alum. cap



SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

SEE C.O.S. NO. <u>899</u>

Surveyor's Seal



certify that the information shown herein is true and correct.

Signature of Ground Party Chief

H. Gene Warren

certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

HUM Wasser
Signature of Surveyor

DIAGRAM OF CORNER:

= Corner recorded on the sheet

2734 S
Registration Number

0

Office of Clerk and Recorder, County of	esla
This "corner record" was filed for record on the day of	July 1981 was noted on the man in land
assigned page No. 10 76 in book No.	July 1981, was noted on the cross-index plat and is  County Official Deputy
	County Official Charty
	Cross Index No. 4. $(7)$ m $4$ $(8)$ $1$ $1$ $2$ $1$ $1$ $1$ $1$ $1$ $1$ $1$ $1$ $1$ $1$