
INSTRUCTIONS



3. Description of monument and accessories set to perpetuate the corner position.

- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of
- 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

CERTIFIED CORNER RECORDATION

Corner: 1/4 Cor.; Secs. 28 & 29

R. 28W. P.M.M. Lincoln County

1903 GLO Record:

Set 3 ft. pine post. Established 2 bearing trees.

1962 Record:

No orig. evidence found.

(Marquardt)

At proportioned position, set brass cap on 2" iron pipe, from which:

A 3/4" iron pipe, bears, North, 20.00 ft., w/ tag marked ES 2989 A 3/4" iron pipe, bears, South, 20.00 ft., w/ tag marked ES 2989

2009 Found:


We find a 2" brass cap, firmly set in good condition, flush with the ground, marked as shown

below. Reference monuments not verified.

2009 Perpetuation:

This 1/4 corner is in a pasture, therefore we establish no reference monuments.

SEE COS NO. 3991



			Sec. 28		
Office of Clerk and Recorder, County of This "corner					_
record" was filed for record or	224829 BOOK: CCR CCGR'S PAGE: 11455 Pages: 1				
RE	ATE OF MONTANA LINCOLN COUNTY CORDED: 03/05/2010 8:58 KOI: CCER'S	•			
	MMY D. LAUER CLERK AND RECORDER E: \$0.00 BY Canput Charles				
= =	: MOBTABA HORTHWEST COMPANY P.O. BOX 8777, MISSOULA, MOBTABA			-	

406-721-4033 Project No. 1617-09