## INSTRUCTIONS

- 1. Original and/or subsequent record used to evaluate the corner position.
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.

3. Description of monument and accessories set to perpetuate the corner position.

- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories,
- 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

## **CERTIFIED CORNER RECORDATION**

Corner: <u>C-E-W-SW 1/256th</u>; Sec. 28

T. 26N.\_\_

R. 28W. P.M.M. Lincoln County

Record:

No previous record

Found:

No evidence found

2009 Perpetuation:

At a position established by the survey and section breakdown of Section 28, we set a 5/8"x30" rebar, 28" in the ground affixed with a 3 1/4" U.S.F.S. alum cap, marked as shown below.

From the monument, we establish the following reference monuments:


A 12" Lodgepole pine, bears N15°W, 34.9.0 ft., scribed CEWSW 1/256 S28 BT An 8" Lodgepole pine, bears N69°E, 16.9 ft., with an "X" cut at breast height

We build a mound of stone around the monument.

We set galvanized steel posts with USFS decals P54-1 & P71-10, approximately 1.0 ft north and east of the monument.

We paint red bands on the bearing trees and attach USFS signs 54-3 & 54-9.

SEE COS NO. 3991



		 Sec.	. 28	
Office of Clerk and Record	der, County of This "corner			
record" was filed for recor	224832 BOOK: CCR CCGR'S PAGE: 11458 Pages: 1 STATE OF MONTANA LINCOLN COUNTY			
was noted on the cross-inc	RECORDED: 03/05/2010 9:01 KOI: CCER'S			
book No.	FEE: \$0.00 BY: Leanon Seans Capity			
	TO: MONTANA NORTHWEST COMPANY P.O. BOX 8777, MISSOULA, MONTANA	 		_

Cross Index No.

<u>U-9.75</u> T. <u>26N</u> R <u>28W</u> PMM

Corner this sheet