## **CERTIFIED LAND CORNER RECORDATION**

(REFERENCE FSH 5681.65)

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)
At the position for the 1/4 corner common to secs. 5 and 4, T. 26 N., R. 28 W.,
I found that original corner stone was gone. A private survey T-iron was set at corner,

## From which:

A 12-inch Douglas-fir snag bears N. 52°30' E., 33 links, scribing "1/4 S 4" visible. (Record: 9-inch fir bears N. 52°30' E., 33 links.)

A 10-inch Douglas fir bears S.  $16^{\circ}$  W., 21 links, scribing "1/4 S 5" visible; tree is alive and in good condition. (Record: 8-inch fir bears S.  $16^{\circ}$  W., 21 links.)

## DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Corner set from original record bearing and distance; I set a 2-inch galvanized iron pipe 26 inches into the ground, with brass cap marked:

I buried private survey T-iron alongside the iron pipe,

From which:

5-inch Douglas-fir bears N.  $82\frac{1}{2}^{0}$  E., 24 links, scribed "S 4 RM."

Date of work: May 21, 1964

T. 26 N., R 28 W.,

858 ES -- IMT -- ART

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.

(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

(Record from original GLO notes.)

Surveyor's Seal

I, .....A. R. Trenkle certify that the information shown herein is true and correct.

Signature of Ground Party Chief

I, Ira M. Tillotson
certify that I have carefully performed or reviewed the
work done on the diagrammed corner as reported on this
recordation form and approve the same;

Signature of Surveyor

DIAGRAM OF CORNER:

() = Corner recorded on the sheet

858ES Registration Number