INSTRUCTIONS

- 1. Original and/or subsequent record used to evaluate the corner position.
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- 3. Description of monument and accessories set to perpetuate the corner position
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.


 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED	CORNER	RECO	RDATI	ON
-----------	--------	------	-------	----

E-W-W 1/256 Secs. 28 & 33 26 N., Corner __ P.M.M County

- No record found
- II. No evidence found

III. At determined position, set a 3/4 ins. diam. aluminum rod, 30 ins. long, 26 ins. in the ground with 3 1/4 ins. diam., U.S.F.S., aluminum cap, marked as shown:




from which

A larch, 21 ins. diam., bears N23 $^{\circ}$ E, 19.2 ft. dist., mkd. E W W 1/256 S28 BT. A spruce, 4 ins. diam., bears N67 $^{\circ}$ E, 20.5 ft. dist., mkd. X BT.

Painted red bands around the bearing trees and attached Land Survey Monument and Bearing Tree signs.

Set a 6 ft. galvanized steel guard post with Land Survey Marker and Property Boundary decals, East, 4 ft.

Magnetic Declination: 20 East



21" LARCH

SKETCH OF CORNER

CERTIFIC	ATION

Alvah F. Hughes

certify that this Corner Record correctly represe

U.S. FOREST SERV

Office of Clerk and Recorder, County of . _ . This "corner 12-15-92 record" was filed for record on ___ was noted on the cross-index plat and is assigned page No. _ Corol M Cummings. book No. -

Cross Index No. .

- corner this sheet