CERTIFIED CORNER RECURDATION

Corner <u>GSS E 1/64 S 5</u> 26 N., R. <u>29</u>W., P.M.M. <u>Lincon</u> County

Record:

None

Found Evidence:

A fence corner approximately 35 ft. North-East of established corner.

Perpetuation:


Set a 5/8 inch diam. rebar 26 inches long with a 11/4 inch YPC stamped: Ked 4975 S, from which:

A 4 1/2 inch DBH Ponderosa Pine bears N 89° W 5.2 ft. distance scribed: X, BT,


A 5 1/2 inch dia. DBH Douglas Fir bears S 74° W 11.7 ft. distance scribed: X, BT.

Painted 6 inch wide red band and attached Bearing tree signs to both trees.

Magnetic Declination: 18° E







CERTIFICATION

entry that rols Corner Record correctly represents work performed by

DAVS

OF SUIVE POT SET STATE OF STATE OF SUIVE POT SET SET SUIVE POT SET SET SUIVE POT SET SET SUIVE POT SET SUIVE POT

Yis Surveying, Inc.

Sketch of Corner

| Section <i>p</i> ' n | |
|--|-------|
| Office of Clerk and Recorder, County of Juncoln | • |
| This "corner record" was filed for record on 11-2700 | |
| was noted on the cross-index plat and is assigned page No in book No | 10454 |
| in book No (blal M. Cumming | Re DA |
| County Official | 300 |



5
54 T 26 N D 29 W PMM • THIS CORNER