# CERTIFIED CORNER RECORDATION

Corner S W 1/16 S 5 T. 26 N., R. 29 W., P.M.M. Lincon County

#### Record:

None

### Found Evidence:

A broken down existing rail fence approximately 12 ft. South of established corner.

## Perpetuation:

Established two new Bearing Trees and set a 5/8 inch diam. rebar 26 inches long with a 1 1/4 inch YPC stamped: Ked 4975 S , from which:


A  $11\frac{1}{4}$  inch DBH Spruce, scribed SW 1/16 S 5 BT Bears N 58° E 12.5 ft. distance,

A 13 3/4 inch DBH Spruce scribed SW 1/16 S 5 BT Bears S 76° E 19.2 ft. distance.

Painted 6 inch wide red band and attached Bearing Tree signs to both trees.

Magnetic Declination: 18° E

Sketch of Corner Spruce



#### Section

Office of Clerk and Recorder, County of

This "corner record" was filed for record on 1/27/80

was noted on the cross-index plat and is assigned page No.

IN DOOK NO.

County Official



