INSTRUCTIONS

- 1. Original and/or subsequent record used to evaluate the corner position.
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
- 3. Description of monument and accessories set to perpetuate the corner position.
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of
- 5. Certification must be signed and scaled by Land Surveyor registered in the State of Montana.

CERTIFIED CORNER RECORDATION

Corner: C-N 1/16th; Sec. 14

T. 26N.

R. 29W. P.M.M. Lincoln County

Record:

No previous record

Found:

No evidence found

2009 Perpetuation:

At a position established by the survey and section breakdown of Section 14, we set a 5/8" rebar, with a 3 1/4" U.S.F.S. alum cap, 0.4 ft. above the ground, marked as shown below, from which we establish the following reference monuments:


> A 9" Douglas fir, bears S86°W, 34.4 ft., scribed CN 1/16 S14 BT A 39" Ponderosa pine, bears N06°W, 21.6 ft., scribed CN 1/16 S14 BT

We build a mound of stone around the monument.

We set a galvanized steel posts with U.S.F.S. decals P54-1 & P71-10, 2.2 ft., south and 2.3 ft., east of the monument.

We paint red bands on the bearing trees and attach U.S.F.S. signs 54-3 & 54-9.

SEE COS NO. 3990



		Sec. 14
Office of Clerk and Recorder,	County of This "corner	
record" was filed for record or	224840 BOOK: CCR CCER'S PAGE: 11466 Pages: 1 STATE OF MONTANA LINCOLN COUNTY	+
	RECORDED: 03/05/2010 9:09 KOI: CCER'S TAMMY D. LAUER CLERK AND RECORDER	
	TO: MONTANA HORTHWEST COMPANY P.O. BOX 8777, MISSOULA, MONTANA	

Cross Index No.

K-19 T. 26N R 29W PMM

Corner this sheet