INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.

2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.

3. Description of monument and accessories set to perpetuate the corner position.

- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories,
- 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

CERTIFIED CORNER RECORDATION

Corner: NW-NW 1/64th; Sec. 34

T. 26N.

R. 29W. P.M.M. Lincoln County

Record:

No previous record

Found:

No evidence found

2009 Perpetuation:

At a position established by the survey and section breakdown of Section 34, we set a 5/8"x30" rebar, 26" in the ground affixed with a 3 1/4" U.S.F.S. alum. cap marked as shown below, from which we establish the following reference monuments:


A 12" Tamarack, bears N70°W, 4.2 ft., scribed NWNW 1/64 S34 BT A 13" Tamarack, bears N51°E, 25.2 ft., with an "X" cut at breast height

We build a mound of stone around the monument.

We set galvanized steel posts with U.S.F.S. decals P54-1 and P71-10, 0.9 ft., east and 0.9 ft., south of the monument.

We paint red bands on the bearing trees and attach USFS signs 54-3 & 54-9.

SEE COS NO. 3992



| | Sec. 34 | | | |
|---|---------|--------------|--|---|
| Office of Clerk and Recorder, County of This "corner | | | | |
| record" was filed for record on 224854 BOOK: CCR CCGR'S PAGE: 11480 Pages: 1 | Ť | + | | H |
| was noted on the cross-index plat. STATE OF MONTANA LINCOLN COUNTY RECORDED: 03/05/2010 9:22 KOI: CCER'S | | \vdash | | |
| book No. MANOY D. LAUER CLERK AND RECORDER | | | | |
| TO: MONTANA NORTHWEST COMPANY P.O. BOX 8777, MISSOULA, MONTANA | | | | J |

Cross Index No.

<u>V.5-13.5</u> T. <u>26N</u> R<u>29W</u> PMM

Corner this sheet