## INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.

2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.

3. Description of monument and accessories set to perpetuate the corner position.

- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories.
- 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

## CERTIFIED CORNER RECORDATION

Corner: N-N 1/64th; Sec. 34

T. 26N.

R. 29W. P.M.M. Lincoln County

Record:

No previous record

Found:

No evidence found

2009 Perpetuation:

At a position established by the survey and section breakdown of Section 34, we set a 5/8"x30" rebar, 26" in the ground w/ 3 1/4" U.S.F.S. alum cap, marked as shown below, from which we establish the following reference monuments:


A 14" Douglas fir, bears S77°W, 3.8 ft., scribed NN 1/64 S34 BT An 8" Douglas fir, bears N24°E, 17.7 ft., with an "X" cut at breast height

We build a mound of stone around the monument.

We set galvanized steel posts with U.S.F.S. decals P54-1 and P71-10, 1.2 ft., west and 0.7 ft., south of the monument.

We paint red bands on the bearing trees and attach USFS signs 54-3 & 54-9.

SEE COS NO. 3992



		Sec. 34		
Office of Clerk and Recorder, County	of This "corner			
record" was filed for record on	224857 BOOK: CCR CC&R'S PAGE: 11483 Pages: 1			$oxed{\mathbb{H}}$
was noted on the cross-index plat and				$\vdash \vdash \vdash$
book No.	TAMMY D. LAUER CLERK AND RECORDER  FEE: \$0.00  BY:  TO: MONTANA NORTHWEST COMPANY P.O. BOX 8777, MISSOULA, MONTANA			

Cross Index No.

<u>V.5-17</u> T. <u>26N</u> R <u>29W</u> PMM

Corner this sheet