INSTRUCTIONS

- 1. Original and/or subsequent record used to evaluate the corner position.
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
- 3. Description of monument and accessories set to perpetuate the corner position.
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories,
- 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

CERTIFIED CORNER RECORDATION

Corner: S-N-N 1/256th; Sec. 34

T. <u>26N.</u>

R. 29W. P.M.M. Lincoln County

Record:

No previous record

Found:

No evidence found

2009 Perpetuation:

At a position established by the survey and section breakdown of Section 34, we set a 5/8"x30" rebar, 26" in the ground w/ 3-1/4" U.S.F.S. alum cap, marked as shown below, from which we establish the following reference monuments:


A 10" Douglas fir, bears N19°E, 18.9 ft., scribed S-N-N 1/256 S34 BT A 10" Douglas fir, bears N79°E, 19.0 ft., with an "X" cut at breast height

We build a mound of stone around the monument.

We set galvanized steel posts with U.S.F.S. decals P54-1 and P71-10, 0.7 ft., east and 1.8 ft., north of the monument.

We paint red bands on the bearing trees and attach USFS signs 54-3 & 54-9.

SEE COS NO. 3992



0.00 0.01 1.70 1.00			Sec. 34		
Office of Clerk and Recorder, Coun	ty of This "corner				
record" was filed for record on	224858 BOOK: CCR CCSR'S PAGE: 11484 Pages: 1			+	
was noted on the cross-index plat ar	STATE OF MONTANA LINCOLN COUNTY			+-	
book No	RECORDED: 03/05/2010 9:26 KOI: CCGR'S TAMMY D. LAUER CLERK AND BECORDER			-	
~	FEE: \$0.00 BY: Sense Sense Legity To: MONTANA HORTHWEST COMPANY P.C. BOX 8777, MISSOULA, MONTANA	-			

Cross Index No.

<u>V.75-13</u> T. <u>26N</u> R <u>29W</u> PMM

Corner this sheet