INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.

2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.

3. Description of monument and accessories set to perpetuate the corner position.

4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of

5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

CERTIFIED CORNER RECORDATION

Corner: C-S-NE-NW 1/256th; Sec. 34

T. <u>26N.</u>

R. 29W. P.M.M. Lincoln County

Record:

No previous record

Found:

No evidence found

2009 Perpetuation:

At a position established by the survey and section breakdown of Section 34, we set a 5/8"x30" rebar, 22" in the ground affixed with a 3 1/4" U.S.F.S. alum cap, marked as shown below, from

which we establish the following reference monuments:


A 12" Douglas fir, bears S71°E, 16.3 ft., with an "X" cut at breast height An 8" Tamarack, bears S32°W, 7.0 ft., scribed CSNENW 1/256 S34 BT

We build a mound of stone around the monument.

We set galvanized steel posts with USFS decals P54-1 & P71-10, south, 1.1 ft. and east, 1.2 ft. of the monument.

We paint red bands on the bearing trees and attach USFS signs 54-3 & 54-9.

SEE COS NO. 3992



		Sec.	34	
Office of Clerk and Recorder, Count	y of This "corner			-
record" was filed for record on	224860 BOOK: CCR CCER'S PAGE: 11486 Pages: 1	 	+	-
was noted on the cross-index plat an		<u></u>	+ +	-
book No.	TAMMY D. LAUER CLERK AND RECORDER FEE: \$0.00 BY: CLERK AND RECORDER TO: MONTANA HORTHWEST COMPANY P.O. BOX 8777, MISSOULA, MONTANA			-

Cross Index No.

<u>V.75-14.5</u> T. <u>26N</u> R<u>29W</u> PMM

Corner this sheet