## **INSTRUCTIONS**

- 1. Original and/or subsequent record used to evaluate the corner position.
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
- 3. Description of monument and accessories set to perpetuate the corner position.
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of
- 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

## CERTIFIED CORNER RECORDATION

Corner: C-S-N-N 1/256th; Sec. 34

T <u>26N</u>

R. 29W. P.M.M. Lincoln County

No previous record

Found:

No evidence found

2009 Perpetuation:

At a position established by the survey and section breakdown of Section 34, we set a 5/8"x30" rebar, 20" in the ground affixed with a 3 1/4" U.S.F.S. alum cap, marked as shown below, from

which we establish the following reference monuments:


A 12" Douglas fir, bears S49°E, 21.4 ft., scribed CSNN 1/256 S34 BT A 17" Douglas fir, bears S78°W, 1.3 ft., with an "X" cut at breast height

We build a mound of stone around the monument.

We set galvanized steel posts with U.S.F.S. decals P54-1 and P71-10, 0.5 ft., north and 0.7 ft., west of the monument.

We paint red bands on the bearing trees and attach USFS signs 54-3 & 54-9.

SEE COS NO. 3992



		S	Sec. 3	34
Office of Clerk and Recorder, C	County of This "corner			
record" was filed for record on	224861 BOOK: CCR CCGR'S PAGE: 11487 Pages: 1		_	<u>_</u>
was noted on the cross-index p	STATE OF MONTANA LINCOLN COUNTY	<b></b>		L
book No.	RECORDED: 03/05/2010 9:29 KOI: CCGR'S TAMMY D. LAUER CLERK AND RECORDER			L
	FEE: \$0.00 BX:			
	TO: MOSTANA HORTHWEST COMPANY, P.O. BOX 8777, MISSOULA, MONTANA			

Cross Index No.

<u>V.75-15</u> T. <u>26N</u> R <u>29W</u> PMM

Corner this sheet