- Description of evidence leand, note discrepancies in the record, state in I of establishing lost or obliterated corner-
- Description of monoment and accessories set to proportion therefore possible set of set to proportion therefore possible set of corner, show all performed data which can best the shown in a second example.
- Certification must be signed and scaled by Registered Land Surveyor in State of Montana
- Fill in Cross Index & Section Diagram at horizon of sheet

## CERTIFIED CORNER RECORDATION

Corner C-E 1/16 Section 9 T. 26 N R. 29 W P.M.M. Lincoln

Date of Work: October 8th, 1982

- 1. No previous record.
- 2. No previous evidence found.
- 3. Set a 5/8 inch diameter x 24 inch long steel rebar with a  $1\frac{1}{4}$ inch diameter yellow PVC Plastic Cap stamped: MDL 4232 S for the C-E 1/16th Corner.

Corner falls in mowed hay field/pasture with no bearing trees available, therefore the following reference monuments were set:


from C-E 1/16th,  $N1^{\circ}22'55$ "E, 92.34 feet, set a 5/8" x 24" steel rebar with yellow cap stamped: MDL 4232 S, bent to North.

from C-E 1/16th,  $S0^{O}19'41"W 167.34 feet, set a <math>5/8" \times 24"$ steel rebar with yellow cap stamped: MDL 4232 S, bent to East.

Both reference monuments set 3-4 inches under existing gravel of the Houghton Creek Road No. 6761.

Set by: KEI

Date: 10/8/82



Cross Index No \_\_\_\_

County Official

r. 26 R. 29

deputi

corner this sheet