- Original and or subsequent record used to evaluate the corner position.

  Description of evaluate to and, note discrepancies in the record, state mediad of evablishing lost or obliterated corners.
- Description of maniment and accessories set to perpetuate the corner position
- Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner madong, topography ites, position of accessories, etc.
- Certification must be signed and sealed by Registered Land Surveyor in State of Montana
- Fill in Cross Index & Section Diagram at bottom of sheet,

## CERTIFIED CORNER RECORDATION

Corner C-N-NW-SE 1/256 Sec. 9T. 26N., R. 29W., P.M.M. Lincoln County

Date of work: January, 1983

- No previous record. 1 .
- 2. No previous evidence found.
- Set a 5/8 inch diameter X 24 inch long steel rebar with a 1/4 inch Э. diameter yellow PVC Plastic Cap stamped: MDL 4232 S for the C-N-NU-SE 1/256 corner.

## From which:

Nothing readily available large enough to nail on a location poster.


All tags posted by K.E.I. Date: 1-4-83

No bearing trees were readily available. Corner falls on the North bank of the Pleasant Valley Fisher River running through a seasonal boggy area with heavy brush and small deciduous growth.

## From which:

A 5 foot long X 3 inch diameter treated post bears North, 4.6 links

A 5 foot long X 3 inch diameter treated post bears East, 6.5 links distant.



County Official Deputy Cross Index No. G, H-11, 12 1. 26 R. 29 corner this sheet