## INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated

corners.

3. Description of monument and accessories set to perpetuate the corner position.

4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

## **CERTIFIED CORNER RECORDATION**

T. \_<sup>26</sup>N C-N-SE 1/64 29W P.M.M. Lincoln County

Set 5/8" X 24" capped steel pin stamped JHN 4661S

Set 10" Ponderoda Pine bearing tree scribed C-N-SE 1/64 BT from which the corner bears S  $07^{\circ}\text{W}$  10.8 ft.

Set 13" Douglas Fir bearing tree scribed C-N-SE 1/64 BT from which the corner bears S  $77^{\circ}$ E 9.6 ft.

Set a location poster on 9" Fir from which the corner bears N 49°E 10.7 ft.

3"DOUGLAS FIR  3"DOUGLAS FIR  STOCK YOUR BT  10" PONDEROSA PINE  C-N-SE Y64 BT  10" PONDEROSA PINE  2" SE Y64 BT  10" PONDEROSA PINE  10" PONDEROS	CERTIFICATION David Stanley  I,
Office of Clerk and Recorder, County of LINCOLN record" was filed for record on the OCTOBER 20	This "corner day of 1983

County Official deputy

T. 26N R. 29W PMM

· - corner this sheet

was noted on the cross-index plat and is assigned page No. 2353

book No.