## INSTITUCTIONS

- 1. Original and/or subsequent record used to evaluate the corner position.
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- corners.

  3. Description of monument and accessories set to perpetuate the corner position.

  4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

  5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

  6. Fill in Cross Index & Section Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION

Corner E 44 COR. SECTION 2 T. ZGN R. Z9W P.M.M. Lincoln County

Oliginal Colner was Replaced with Beass Cap in 1964, set By B.L.M.


Remaining Bearing Thees A ZO" Pine Beaks N8034°W, GO.7' (malks visable)
A 7" Fir stump Bears N 40°W, 74.6' (Burned in Fir, marks not visable.)

Set New Monument As shown Below.

A 2'E" OIA. Alum. Cop on Alum, Pipe was: set 2' Deap in a Glaveli Bak of the Fishel Rivel with concrete pouled as Fill in hole. set Balvinized steel Post on West side of monument.

Placed New BT. Tag on Zo" Pinc which Beaks N80340W, 60.7' Placed BT. Tag on Lost wood RAIL Fence Post. 15.5 FT. FROM MONUMENT.





• · corner this sheet

... R. ...

. PMM

Cross Index No. -