INSTRUCTIONS

- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
 - escription of monument and accessories set to perpetuate the corner position
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.


 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

	Corn	er	WC W	/-E-W 1	/256 s	30			T. <u>26 n.</u> ,	R	29 W.,	_ P.M.M	Linco <u>ln</u>	(County
Ι.	No	prev	ious	record	found	at	Lincoln	County	Courthouse.						

No evidence found.

III. The position for the W-E-W 1/256 cor., determined by single proportion measurement, falls in the Silver Butte Fisher River, therefore I set a 3/4 in. diam. X 30 ins. long driveable alum. rod, 12 ins. in the ground, with a 3 1/4 in. diam. alum. cap mkd. as shown below, 30.0 ft EAST, on line between the N 1/4 Sec. 30 and the W-E-W 1/256 Sec. 30, as a witness corner to the W-E-W 1/256.



Build a collar of stone around the monument.

Establish two new bearing trees:

A cottonwood, 10 ins. dia., bears N 32° E, 39.1 ft. dist., mkd. WC W E W 1/256 s30 BT. A larch, 15 ins. dia., bears S 86° E, 82.6 ft. dist., mkd. WC W E W 1/256 S30 BT.

Painted a red band around each bearing tree and attached Land Survey Monument and Bearing Tree signs.

Set a 6 ft. galvanized steel guard post with Land Survey Marker and Property Boundary decals attached, East, 3 ft. dist.

Magnetic Declination: East, 20

book No.

Refer to the Certificate of Survey filed at the Lincoln County Courthouse.

