
INSTRUCTIONS

- Original and/or subsequent record used to evaluate the corner position.
 Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- 3. Description of monument and accessories set to perpetuate the corner position.
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
- 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

CN 1/16 S 30 Lincoln Corner_ 1992 Certificate of Survey No. 1330 by D. K. Marquardt: Set a 5/8 in. diam. X 24 in. long rebar with a plastic cap stamped 2989 ES. II. Found a 5/8 in. diam. rebar, firmly set with yellow plastic cap mkd. D. K. MARQUARDT 2989 ES. A 6 ft. galvanized steel post bears WEST, 0.5 ft. with "Land Survey Marker" and "Property Boundary" decals.

III. I accept the position of the found rebar and replace it with a 3/4 in. diam. X 30 in. long driveable alum. rod, 24 ins. in the ground, with a 3 1/4 in. diam. alum. cap mkd as shown:



Bury the rebar alongside the aluminum rod.

Establish two new bearing trees:

A pine, 9 ins. diam., bears N 16° E, 39.1 ft. dist., mkd. CN 1/16 S 30 BT. A larch, 7 ins. diam., bears N 74° E, 26.0 ft. dist., mkd. CN 1/16 S 30 BT.

Painted a red band around each bearing tree and attached Land Survey Monument and Bearing Tree

No guard post established.

Magnetic Declination: East, 20

N7VE A	Kenneth R. Keneth R. Kenet	round Party Chief nes correctly represents work performed in compliance with the "Corner seq., M.G.
SKETCH OF CORNER	Employer: U.S. FORES	ST SERVICES FER. 1.
Office of Clerk and Recorder, County of Jincoln record' was filed for record on Mark 24	. This "corner	Sec. 30
was noted on the cross-index plat and is assigned page No book No County Office	6219 , in	
s-3	26 N 29 W	• - corner this sheet