## INSTRUCTIONS

- 1. Original and/or subsequent record used to evaluate the corner position
- Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.

Description of monument and accessories set to perpetuate the corner position.

- 4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
  - . Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

5. Fill in Cross Index & Section Diagram at bottom of sheet,

## CERTIFIED CORNER RECORDATION

SW corner Sec. 24	26N	_ 30W	Lincoln	
Corner	Т	R	. P.M.M	County

1. 79.62 chains: Set slate stone 14 X 12 X 5 ins., 10 ins., in the ground for corner of secs. 23,24,25 and 26 marked with 2 notches on S. and one notch on E.

edge; and raise a mound of stone 2 ft. base 1½ ft. high west of corner. Corner falls on top of ridge bearing NW and SE from the corner, a Tamarack 24 ins. diameter, bears N 49 3/4°E 49 links distance marked T 26N.,R. 30W S 24 B.T. a Tamarack 8 ins. diameter, bears S 15 3/4°E 110 links distance marked T 26 N.,R. 30 W S 25 B.T. a Tamarack 18 ins. diameter, bears S 42°W 18 links distance marked T 26 N.,R. 30 W. S 26 B.T. a Pine 6 ins. diameter, bears N 28°W 16 links distance marked T 26N.,R. 30W. S 23 B.T.

- 2. Found: original stone with 2 notches on south and one on east. No mound or bearing trees. Corner had been flagged by U.S.F.S. crew.
- 3. I replace stone with a 3" aluminum monument on a 30" pipe from which a 4" L.P. Pine bears N 12°W 15.3 feet scribed S 23 B.T. and posted. A 3" Pine bears N 72°E 7.6 feet scribed S 24 B.T. posted. A 4" L.P. Pine bears S 45°E 5.3 ft. scribed S 25 B.T. and posted. A 3" Pine bears S 55°W 11.2 feet scribed S 26 B.T. and posted.

Note: There were no trees of suitable size, in range, but we felt that marking and posting smaller trees (which were numerous) we might help to perpetuate the location of this corner.



book No.

Set a 3" aluminum monument marked as shown.

10 4661 2 18 18 18 18 18 18 18 18 18 18 18 18 18	
4" L.P. PINE	CERTIFICATION
30	certify the information shown herein is true and correct
FOUND ORIG STORE WIN	• • • • • • • • • • • • • • • • • • •
ENOTCHES ON ST	Signature Ground Party Chief
REPLACED WITH MON. AS SHOWAI ABOVE. 3"L.P. PINE 9	1. Jack H. Ninneman  certify that this Corner Record corrective represents work performed by me or under by direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.)  Signature of Surveys & Scall  Date: 10/7/81 Reg. No. 4661S.  Ninneman Engineering Inc.
SKETCH OF CORNER	
Office of Clerk and Recorder, County of Lincoln	This "corner Sec. 24
record" was filed for record on the November 512	day of 192/
was noted on the cross-index plat and is assigned page No. 13	5/ in $-+-+-+$

L. Vaughn by

County Official

30W

corner this sheet