INSTRUCTIONS

- 1. Original and/or subsequent record used to evaluate the corner position.
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- Description of monument and accessories set to perpetuate the corner position.
 Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- 5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

P.M.M. Lincoln East 1/4 corner Sec. 24 T. 26N R. 30W 1. 40 Chains: Set an iron post 3 ft. long 1 in. in diameter 24 ins. in the ground for & Section Corner for Sec. 24 only with brass cap marked 4S24 1916 and raise a mound of stone 2 ft. base $1^{\frac{1}{2}}$ feet high W. of corner. 2. Found: 1916 brass cap from which a 6" Larch bears N 512°E 32 links scribed "X" B.T. a 9" Larch bears N 620W 38 links both trees posted by Art 1968. 3. Painted corner monument and bearing trees with bright red paint.



(LARCH CERTIFICATION Jack H. Ninneman certify the information shown herein is true and correct. Signature Ground Party Chief Jack H. Ninneman certify that this Corner Record correctly represents work performed by me or under by direction in compilance with the Recordation Act" (70-22-101, et seq., M.D.A.) Signature of Surveyor & Seal Date: 9/25/81 Reg. No. 4661S Employer: Ninneman Engineering Inc. **SKETCH OF CORNER**

\mathscr{S}^{*} ρ .	Sec. 24	
Office of Clerk and Recorder, County of Lincoln . This "corner		
3. Z/A	1 i	: i I
record" was filed for record on the Milenber 577 day of 1987	 	╀╌╺╌┼╌╶┤
was noted on the cross-index plat and is assigned page No	+	-
		!![
book No Eleanor L. (bugher by Detty & Concer	<u> </u>	┡╶┼╴┤
book No. / Eleanor L. Laugher by Betty from County Official Deposition	1 !	
Do-	<u></u>	
Cross Index No. 7 26N R. 30W PMM	• - corner	this sheet