## INSTRUCTIONS

- Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
- 3. Description of monument and accessories set to perpetuate the corner position.
- Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- Certification must be signed and scaled by Registered Land Surveyor in State of Montana.
   Fill in Cross Index & Section Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION

Corner <u>C-S-S-S 1/256 cor. Sec. 34</u> 26N Lincoln County

- 1. This corner not previously set.
- 2.Set: a 3" X 30" aluminum capped monument marked as shown below from which,
  A 10" Pine bears N 75 E 8.8 feet scribed C-S-S-S 1/256 S34B.T. and posted.
  A 6" Larch bears S 66 W 2.3 feet scribed C-S-S-S 1/256 S34B.T. and posted. A location poster on a 4" Larch bears N 55°E 3.7 feet. Painted monument and accessories with bright red paint.



Set 3" aluminum monument marked as shown.

A LOCATION POSTER ON A 4" LARCH BOARS N 55° E 3.7 FT.  SET AN ALWAINUM MONUMENT 3" x 30" MARKED AS SHOWN.  6" LARCH SKETCH OF CORNER	CERTIFICATION  1. Jeff Paullin certify the information shown herein is true and correct.  Signature Ground Party Chief  1. Jack H. Ninneman ' certify that this Corner Record correctly represents work performed by me or under by direction in compliance with (se "Corner Recordation Act" (70-22-101, et seq., M.D.A.)  Signature of Surveyor & Sea!  June '82 Reg. No.  Employer: Ninneman Engineering Inc.
Office of Clerk and Recorder, County of Lincol	Sec. 34
record" was filed for record on the	day of 1962
book No. Eleanor L Vaughe L County Office	