- Original and/or subsequent record used to evaluate the corner position.
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- 3. Description of monument and accessories set to perpetuate the corner position
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- 5. Certification must be signed and scaled by Land Surveyor registered in the State of Montana.
  6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED	CORNER	RECORD	ATION
-----------	--------	--------	-------

S. 1/4 OF SEC. 33 (only) Lincoln Corner. County

1916 G.L.O. record by Carl Dyson: "Set an iron post, 3 ft. long, 1 in. in diam., 24 ins. in the ground, for 1/4 sec. cor. for sec. 33 only, with brass cap marked



and raise a mound of stone, 2 ft. base, 1 1/2 ft. high, N. of cor."

II. Found a 1 in. diam. iron pipe, 18 ins. out of ground, with 2 1/4 ins. diam. G.L.O. brass cap,



from which:

A mound of stone, 2 ft. base by 1 1/2 ft. high, bears N. of cor.

III. Establish two new bearing trees:

A fir, 12 ins. diam., bears  $N52^{\circ}E$ , 24.6 ft. dist., mkd. 1/4 S33 BT. A hemlock, 6 ins. diam., bears N38 W, 11.5 ft. dist., mkd. "X" in snow blaze and "BT" at base.

Painted red bands around the bearing trees and attached Land Survey Monument and Bearing Tree signs.

Magnetic Declination: 20 East

## **SKETCH OF CORNER**

CERTIFICATION

certify that this Corner Record correctly re-

U.S. FOREST

Office of Clerk and Recorder, County of . This "corner 12-14-92 record" was filed for record on \_\_\_ was noted on the cross-index plat and is assigned page No.

book No. -

Cross Index No.

corner this sheet