

## INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION

Corner SE-NE 1/64 S29 T. 26 N. R. 32 W. P.M.M. Sanders County


I. 1990 BLM records: BLM plat and records not approved at this date.

II. Found a 2 1/2 ins. diam. iron pipe, 2 ins. above ground with 3 1/4 ins. diam., BLM brass cap, marked as shown:



Monument located in a road cut slope with stone collar.

III. Painted red bands around the bearing trees and attached Land Survey Monument and Bearing Tree signs.



## CERTIFICATION

I, Kevin A. Todd  
certify the information shown herein is true and correct.

Kevin A. Todd  
Signature Ground Party Chief

I, Ronald A. Pearson  
certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.C.A.)

Ronald A. Pearson  
Signature of Surveyor & Seal

Date: 12/17/92 Reg. No. 9008LS


Employer: U.S. FOREST SERVICE

## SKETCH OF CORNER

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on 1-4-93 was noted on the cross-index plat and is assigned page No. 5226, in book No. Coral M. Cummings, Reg. 113 County Official

Cross Index No. 5S-8.50 T. 26 N. R. 32 W. P.M.M.

Sec. 29



• - corner this sheet