-	CERTIFIED CORNER RECORDATION				
	C 1/16 Coo 24 27 N 26 W ELATUEAD				
	·				
[.	Record: 1902 Original G.L.O. Subdivision of Township 27 North. Range 26 West. by Burton S. Adams;  1980 Certified Corner Recordation by Stephen D. Staab. Reg. No. 5619S; No previous record.				
	Set a 2 1/2"x30" aluminum pipe with cap marked as shown:  Raise a mound of stone around cap.  R26W R25W  S 1/16				
	From which:				
	A 8" fir, bears N23"W, 25.8 ft., marked S 1/16 S24 BT.  A 12" tamarack, bears S58"W, 14.5 ft., marked S 1/16 S24 BT.				
	Attached signs and painted a 6" red band around trees. Placed a National Forest Boundary sign next to the corner.				
	1994 Certified Corner Recordation by Alvah F. Hughes, Reg. No. 7322LS; Found a 2 1/2 in. diam. aluminum pipe, firmly set, with a 3 1/4 in. diam. aluminum cap, 6 ins. above ground, marked as shown above,				
	from which:				
	A larch 16 ins., bears S60°W, 14.8 ft., visible scribing. A spruce snag, 8 ins. daim., bears N18°W, 26.0 ft., marked S 1/16 BT.				
	Established one new beraing tree:				
	A larch 12", bears N24W, 22.4 ft., marked S 1/16 BT.				
	Painted a red band around bearing trees and attached Land Survey Monument and Bearing Tree signs.				
	Set a 6 ft. galvanized steel guard post with Land Survey Monument and Property Boundary decals, WEST, 1 ft.				
	Magnetic Declination 20° East				
II.	Found: A $2\ 1/2\ \text{in.}$ diam. aluminum pipe, $8\ \text{ins.}$ above ground, with a $3\ 1/4\ \text{in.}$ diam. aluminum cap marked as shown above,				
•	from which:				
	A larch 16 ins., bears S58W, 14.5 ft., healed face. A larch snag, 11 ins. daim., bears N24W, 22.4 ft., marked S 1/16 S24 BT.				
III.	Established one new berging tree:				
	A spruce 9", bears N83"W, 36.4 ft., marked S 1/16 S24 BT.				
	Painted a red band around bearing trees and attached Land Survey Monument and Bearing Tree signs ROGER O. GREEN 13769LS				
	Date of Fieldwork: 7/29/2004 Survey crew: Steve Boyer, Tom Hommel Magnetic declination: 18' East assumed Equipment used: Hand compass and loggers tape				
	U.S. Forest Service, Supervisiors Office, 1101 Hwy. 2 West, Libby, MT 59923 (406) 293-6211				
	CERTIFICATION  Steven A. Boyer 9750LS				
	certify the internation shown herein is true and correct.				
	Signature Ground Porty Chief				
	Roger O. Green certify that this Corner Record correctly represents work				
	N83W  Derformed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.C.A.)				
	Signature of Surveyor & Seel				
	Date: 07/29/2004 Reg. No13769LS				
<u>SK</u> E	TCH OF CORNER NOT TO SCALE Employer. U. S. Forest Service				
	Office of Clerk and Recorder, County of <u>Flathead</u> . This "corner				

182248 BOOK: CCR CCER'S PAGE: 10773 Pages: 1 record" was filed STATE OF MONTANA LINCOLN COUNTY was noted on the RECORDED: 02/02/2005 9:08 KOI: CCGR'S RECORDED: 02/02/2005 9:08 KUI: CCAR
CORAL M. CUMMINGS CLERK AND RECORDER
FEE: \$0.00 BY:
To: FILED , book No. FEE: \$0.00 \_т. **27N.**<sub>R.</sub> **26W.** <sub>Р.М., мт</sub> Q-25 Cross Index No.\_ Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors corner this sheet

## CERTIFIED CORNER RECORDATION Corner SE Sec. Cor. Sec. 23 T 27 N. R. 26 W. P.M.M. FLATHEAD County II. Found: 2 1/2 in. diam. aluminum pipe, 6 ins. above ground, firmly set, with a 3 1/4 in. diam. aluminum cap marked as shown, from which: A larch, 26 ins. diam., bears N32°E, 89.8 ft. dist., with 6 24 visible. A larch, 26 ins. diam., bears S57°E, 12.5 ft. dist., marked with a healed face. A larch, 29 ins. diam., bears S75°W, 91.4 ft. dist., with 6 visible. A grand fir snag, 8 ins. diam., bears N77°W, 10.4 ft. dist., marked with a healed face. III. Establish one bearing tree:

Painted a 6 in. red band around bearing trees and attached Land Survey Monument and Bearing Tree signs.

A larch, 9 ins. diam., bears N13W, 10.1 ft. dist., marked T27N R26W S23 BT.

Date of Fieldwork: 7/13/2004
Survey crew: Steve Boyer, Tom Hommel
Magnetic declination: 18' East assumed
Equipment used: Hand compass and loggers tape
U.S. Forest Service, Supervisiors Office, 1101 Hwy. 2 West, Libby, MT 59923 (406) 293—6211

CERTIFICATION

Stevan A. Boyer 9750LS

certify the information shown harein is true and correct.

Signature Ground Porty Chief

Roger O. Green

certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act (19-22-101, et seq., M.C.A.)

Bignature of Surveyor & Seal

Date: 07/13/2004 Reg. No. 13769LS

Employer: U. S. Forest Service

Office of Clerk and Recorder, County of Flathead

This "corner Total Record."

KETCH OF CORNER	NOT TO SCALE	Employer: U. S. FO	rest Service
Office of Clerk and Recorder, County of	Flathead This "c		T27N R26W
was noted on the cross—index plat and is a book No.			Soc. 23——Soc. 24—
County Official			Sec. 26 Sec. 25
Cross Index No.	R-21 <sub>T.</sub> 27N. <sub>R.</sub>	26W. P.M., MT	
Adopted July 1, 1981, Montana Board	of Professional Engineers &	: Land Surveyors	corner this sheet