
	E 4 /46	35								
Corner	E 1/16	2	Т	27	N.	R	29 W.	РММ	LINCOLN	County

- I. 1988 Certified Corner Recordation by Linda Smith, MT Reg. No. 6296S; No original record of corner. No evidence found in the field. At midpoint between 1/4 cor. of secs. 2 and 35 and sec. cor of secs. 1, 2, 35 and 36, set an aluminum rod, 3/4 ins. diam., 30 ins. long, 26 ins. in the ground with a 3 1/4 in. diam. aluminum, U.S.D.A., Forest Service cap marked as shown. (See below) No bearing trees available because of the Houghton Creek fire in the area. Set a guard post with "Land Survey Marker" and "Property Boundary" decal, 3 ft. East.
- II. Found, a 5/8 in. diam. aluminum rod with a 3 1/4 in. diam. aluminum cap firmly set in a collar of stone, 3 ins. above ground, with cap marked as shown below. Steel guard post with "Land Survey Marker" and "Property Boundary" decal, 3 ft. East.
- III. Establish 2 new bearing tree:

A pine, 6 ins. diam., bears S36'W, 21.4 ft. dist., mkd. E 1/16 S2 BT. A pine, 5 ins. diam., bears N72'W, 20.0 ft. dist., mkd. "X" BT.

Painted the scribed faces red and 6 in. wide red bands around the bearing trees. Attached Land Survey Monument and Bearing Tree signs. Set a 6 ft. steel guard post South, 3 ft. with Land Survey Monument and Property Boundary decal attached.

LAT 48'03'10.80420"N LONG 115"17'43.80956"W NAD 83





Date of Fieldwork: 4/26/2011 Survey crew: Tom Hommel

Magnetic declination: 20' East assumed

Equipment used: Hand compass and loggers tape

U.S. Forest Service, Supervisors Office, 31374 Hwy. 2, Libby, MT 59923 (406) 293-6211





Office of Clerk and Recorder, County of Lincoln

237361 BOOK: CCR CCGR'S PAGE: 11946 Pages: 1

STATE OF MONTANA LINCOLN COUNTY

RECORDED: 02/22/2012 9:15 KOI: CC&R'S

TAMMY D. LAUER CLERK AND RECORDER

FEE: \$0.00 TO: FILED ,

Cross Index No.

Z 20 t. 27N. r. 29W. p.m.

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

Sec. 35

corner this sheet