INSTRUCTIONS

ent record used to evaluate the corner position. quent record used to evaluate the count, state method of est corners.
3. Description of monument and ac

ories set to perpetuate the corner position

4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking topography ties, position of accessories, etc.

5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

# **CERTIFIED CORNER RECORDATION**

Corner 1/4 cor. sec. 34 and 3 T. 27N R. 29W P.M.M. Lincoln \_\_\_\_County

## Record 1902

Set a lime stone 15x10x5 ins., 10 ins. in the ground for 4 cor. marked 1/4 on N face; from which;

A fir,10 ins. dia. bears N46 $^{\circ}$ 45'E, 27 lks. dist. marked ½ S34 BT A fir,10 ins. dia. bears S23 $^{\circ}$ W, 21 lks. dist. marked ½ S3 BT

## Record 1966 B.L.M.

The ¼ sec. cor. of secs. 3 and 34 on the N. bdy. of the Tp., monumented with a limestone, 16x10x6 ins., firmly set, marked with  $\frac{1}{4}$  on the N. face and witnessed by the remains of one of the original bearing trees. At the corner point. Set a iron post, 30" long, 2½" dia., 24" in the ground, with a brass cap marked as shown below. From which;

The original bearing trees: A dead fir, 12" dia. bears S23°W, 21 lks. dist. marked 1/4 S3 BT

The new bearing trees: A larch, 8" dia., bears S3°W, 27 lks. dist. marked ½ S3 BT A larch, 14" dia., bears N27½°W, 50 lks. dist. marked ½ S34 BT Bury the original stone alongside the iron post.

### FOUND

Found a standard B.L.M. brass cap on a steel post, standing dead 8" tamarack S5 W 18.0' scribing partly readable, Dead and down 14" tamarack N26 W 33.0' scribed  $\frac{1}{4}$  S34 BT, No original BTs found

### NEW BEARING OBJECTS

A U.S.D.A. 6' steel post set 18" into the ground bears South 13.45' A U.S.D.A. 6' steel post set 18" into the ground bears North 13.50' Attached required signs to bearing objects. a U.S.D.A. 6' steel post set 18" into the ground bears West 3' with Land Survey Monument sticker

note: no live trees within 400' radius.

