CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

Section Corner common to sections 17,18,19 and 20 Twp. 27 N., R. 29 W P.M.M. destroyed.

> DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

> > Date of work: 12/18/80.....

See sketch on reverse side

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

See sketch on reverse side.

DIAGRAM OF CORNER: I, David Stanley Surveyor's Seal certify that the information shown herein is true and Signature of Ground Party Chief 18 20 I, ...lack H. Ninneman certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same. = Corner recorded on the sheet Signature of Surveyor

> 46615 Registration Number

> > N-3


N-5

P-5

This "corner record" was filed for record on the 25 and day of 19 Min, was noted on the cross-index plat and is ., in book No. T. 27N Cross Index No. J-5

3 Form 125—7887

TWP. 27N., R. 29W. P.M.M.



- (1) B.L.M. B.C. 4 B.T.s
- (2) Corner destroyed position computed. Not set.
- (3) Set a Brass Cap from which a 50" Cottonwood bears N 73° E 29.6 feet Scribed S 17 B.T. and posted. A 20" Cottonwood bears S 58°30' E 31.1 feet Scribed S 20 B.T. and posted.
- (4) B.L.M. B.C. 1 B.T.
- (5) B.L.M. B.C. 2 B.T.s
- (6) B.L.M. B.C. 2 B.T.s

