
CERTIFIED CORNER RECORDATION

Corner SE-NW 1/256 S2 T 27 N. R. 30 W. P.M.M. LINCOLN County

- I. Record: No previous survey.
- II. Found: No evidence found.
- III. At the corner point

 Set an iron rebar, 24 ins. long, 5/8 ins. diam., 30 ins. in the ground, with a 3 1/4 ins. diam., aluminum U.S.F.S cap mkd. as shown:



From which:

A fir, 8 ins. diam., bears S89°E, 19.6 ft. dist., mkd. SENW 1/64 S2 BT. A pine, 8 ins. diam., bears S38°E, 59.4 ft. dist., mkd. "X" BT.


Set 2, 4 in. x 4 in. wood posts, 25 ft. south and east of the corner, with Property Boundary and Land Survey Monument signs attached. Painted red bands around BT's and attached Bearing Tree and Land Survey Monument signs.

Survey crew: Steve Boyer, Tom Hommel

Magnetic declination: 20' East assumed

Equipment used: Hand compass and loggers tape

U. S. Forest Service, Supervisiors Office, 1101 Hwy. 2 West, Libby, MT. 59923 (406)



CERTIFICATION

Steven A. Boyer 9750LS
certify the information shown herein is true and correct.

Signature Ground Party Chief

Roger O. Green
certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-181, et seq., M.C.A.)

Signature of Surveyor & Seal


Date: 1/24/2001 Reg. No. 13769LS

Employer: U. S. Forest Service

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on $\frac{35}{200}$, was noted on the cross-index plat and is assigned page No. $\frac{10499}{200}$, in book No. $\frac{10499}{200}$ County Official

Cross Index No. $\underline{B.5-18.5}$ T. $\underline{27N.}$ R. $\underline{30W.}$ P.M., MT

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors



MATMON

ROGER: 0.

GREEN

13769LS

· corner this sheet