
CERTIFIED CORNER RECORDATION

Corner C-S-SE-NW 1/256 S2 T 27 N. R. 30 W. P.M.M. LINCOLN County

- I. Record: No previous survey.
- II. Found: No evidence found.
- III. At the corner point
 Set an iron rebar, 24 ins. long, 5/8 ins. diam., 25 ins. in the ground, with a 3 1/4 ins. diam., aluminum U.S.F.S cap mkd. as shown:



From which:

A larch, 10 ins. diam., bears N13°E, 112.5 ft. dist., mkd. CSSENW 1/256 S2 BT. A pine, 18 ins. diam., bears N89°E, 61.6 ft. dist., mkd. "X" BT.

Set 2, 4 in. x 4 in. wood posts, 3 ft. north and east of the corner, with Property Boundary and Land Survey Monument signs attached. Painted red bands around BT's and attached Bearing Tree and Land Survey Monument signs.


Survey crew: Steve Boyer, Tom Hommel

Magnetic declination: 20' East assumed

Equipment used: Hand compass and loggers tape

U. S. Forest Service, Supervisiors Office, 1101 Hwy. 2 West, Libby, MT. 59923





CERTIFICATION

Steven A. Boyer 9750LS

certify the information, shown herein is true and correct.

Signature Ground Party Chief

Roger O. Green

certify that this Comer Record correctly represents work performed by me or under my direction in compliance with the "Cerner Recordation Act" (70-22-101, et seq., M.C.A.)

Agnature of Surveyor & Seal

Date: 1/24/2001 Reg. No. 13769LS

Employer: U. S. Forest Service

Office of Clerk and Recorder, County of Lincoln ... This "corner record" was filed for record on Jan 35, 200/
was noted on the cross-index plat and is assigned page No. 10501 in book No.

County Official

Cross Index No. <u>B.75-18.5</u> T. <u>27N. R. <u>30W.</u> P.M., MT Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors</u>

Sec. 2

corner this sheet