Corner this sheet

INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.

Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.

- Description of monument and accessories set to perpetuate the corner position.

 Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of 4. accessories, etc.
- Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner W 1/16 Sec. 12 & 13

T. 27 N., R. 30 W., P.M.M. **Lincoln** County

RECORD:

(1992) Corner Recordation, 7322LS Hughes

Set 21/2" diam. Aluminum pipe 5" below the surface of the ground with attached 3 1/4" U.S.D.A. Forest Service Aluminum cap marked W1/16, S12, S13, 7322LS, 1992. Located in a hayfield with no suitable bearing trees within reasonable limits, from which:

Set a 6 ft. galvanized steel guard post with "Land Survey Monument" and "Property Boundary" decals bears East 4 ft.

Location poster on a wood fence post N. 68°E., 18.7ft. dist.

FOUND

A 3 1/4" AC. Marked as shown below, from which a Location poster on a wood fence post bears N.70°E., 18.7 ft.

A disturbed witness post was found nearby.

SET

Set a B.T. Tag on a wooden fence post bears S.16° W., 4.6 ft.

Fnd. Location poster on wooden fence post FND. 31/4" ALUMINUM MARKED CAP Bearings by Silva compass 20 ° E. Decl. Distance by fiberglass tape Set, BT tag on wooden fence post

