
## CERTIFIED CORNER RECORDATION

Corner \_\_\_\_\_NW 1/16 S2 \_\_\_\_\_T\_\_27 N. R. \_\_\_\_30 W . P.M.M. \_LINCOLN \_County

- I. Record: No previous survey.
- II. Found: No evidence found.
- III. Set: At the position determined by survey, set a 5/8" by 24" steel rebar, 20" in the ground with a 3 1/4" diameter aluminum U.S.F.S cap marked as shown:



From which:

A fir, 10 ins. diam., bears N88°E, 36.6 ft. dist., mkd. NW 1/16 S2 BT. A fir, 9 ins. diam., bears N9°W, 4.3 ft. dist., mkd. NW 1/16 S2 BT. Monument is set in a rock outcrop.


Painted red bands around BT's and attached Bearing Tree and Land Survey Monument signs.

Date of Fieldwork: 9/18/2001

Survey crew: Steve Boyer, Tom Hommel Magnetic declination: 20° East assumed


Equipment used: Hand compass and loggers tape

U.S. Forest Service, Supervisiors Office, 1101 Hwy. 2 West, Libby, MT 59923 (406) 293-6211



SKETCH OF CORNER

NOT TO SCALE




Office of Clerk and Recorder, County of Lincoln
This "corner record" was filed for record on Teb 19 2002

was noted on the cross-index plat and is assigned page No. 10550, in book No.

County Official

Cross Index No. <u>B-18</u> T. <u>27N.</u> R. <u>30W.</u> P.M., MT

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors



corner this sheet