- Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners
- Description of monument and accessories set to perpetuate the corner position.

 Sketch or corner, show all perturent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- Certification must be signed and seated by Registered Land Surveyor in State of Montana.
- 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner E 1/16th Section 23 T. 27 N., R. 30 W., P.M.M. Lincoln County

Date of Work: 9/15/83


- No previous record. 1.
- 2. No evidence found.
- Set a 2 1/2 inch diam. X 30 inch long Aluminum post with lower half crimped and with a 3 1/4 inch diam. Aluminum Cap marked as shown Э. below in sketch of corner; set 6 to 7 inches, more or less, above ground with small dirt mound around corner; no rock readily available; painted corner flourescent orange and tied blue flagging around it.

From which:

- A Lodgepole Pine, & inches in diam., bears N. 18 1/20 W., 7.0 feet distant, marked: E 1/16 S23 BT
- A Lodgepole Pine, 7 inches in diam., bears S. 240 W., 9.5 feet distant, marked: E 1/16 S26 BT

Bearing trees tagged with U.S.F.S. interior location posters; with faces of scribed blazes and snow blazes painted flourescent ornage and flourescent orange ring painted above tags.

NOTE: Corner falls on a flat bench in the bottom of the main drainage of Miller Creek approximately 130-150 feet South of Miller Creek.



Office of Clerk and Recorder, Count	y of LINCOLN	. This "corner record"	Sec. 23-T27N-R 30W-PMN
was filed for record on the 19th day		oted on the cross-index plat and	
is assigned page No. <u>3337</u> , in b	ook No <i>Clanet b</i>	County Official deputy	
	Cross Index No.	<u>г. 27</u> r. <u>30</u> рмм	

· - corner this sheet