- Original and/or subsec ent record used to evaluate the corner position.
- Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
- Description of monument and accessories set to perpetuate the corner position.

 Sketch of corner, show all perfinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- Certification must be signed and sealed by Registered Land Surveyor in State of Montana,
- Fill in Cross Index & Section Dingram at bottom of sheet,

CERTIFIED CORNER RECORDATION

Corner_CS 1/16th Section 23 T. 27N., R. 30W., P.M.M. Lincoln County Date of Work: 9/15/83


- 1. No previous record.
- 2. No evidence found.
- Set a 2 1/2 inch diam. X 30 inch long Aluminum Post with lower half crimped and with a 3 1/4 inch diam. Aluminum Cap marked as shown below in sketch of corner; set 6 to 9 inches, more or less, above 3. ground with small dirt mound around corner; no rock readily available; corner painted red with blue flagging tied around it.

From which:

- A Tamarack, 9 inches in diam., bears N. 46 1/20 E., 32.9 feet distant, marked: TB ES2 41\1 23
- A Tamarack, 10 inches in diam., bears N. 12 1/20 W., 10.2 feet TB JIL 23 CS 1/16 BT

Bearing trees tagged with St. Regis location posters; with faces of scribed blazes and snow blazes painted red and red ring painted above tags.

Corner falls on a gentle slope rising above Miller Creek NOTE: on the North side of Miller Creek and the Miller Creek Road.



Office of Clerk and Recorder, County of LINCOLN . This "corner record" Sec. 23-T27N-R30W-PMM was filed for record on the 19th day of SEPT 1983, was noted on the cross-index plat and is assigned page No. <u>2339</u>, in book No. Canet BI Siegel by County Official 23 г. <u>27</u> R. <u>30</u> РММ