
CERTIFIED CORNER RECORDATION

Corner MS 8995 COR. 2 Sec. 12 T. 27N R. 31W P.M., MT. Lincoln County Y.J. LODE

- I. 1909 Original Mineral Survey No. 8995 by Aurthur E. Lee et al: Cor. No. 2. A tamarack post 4 ft. long, 4 ins. sq., 2 ft. in the ground, with mound of stone, scribed Y.J. 2-8995.
 - A blazed dead fir tree, 14 ins. diam., bears S 76°W, 15.8 ft. dist., scribed B.T. Y.J. 2-8995. A blazed dead tamarack tree, 12 ins. diam., bears N 10°W, 54.0 ft. dist., scribed B.T. Y.J. 2-8995.
- II. No evidence found.
- III. At the position determined by survey, set a 2 1/2 in. diam. alum. pipe, 30 ins. long, 26 ins. in the ground with a 3 1/4 in. diam. alum. cap mkd. as shown:




from which:

A hemlock, 9 ins. diam., bears S68°W, 18.0 ft. dist., mkd. "2 YJ 8995 BT". A fir, 8 ins. diam., bears N50°W, 14.5 ft. dist., mkd. "2 YJ 8995 BT".

Painted red bands around the bearing trees and attached Land Survey Monument and Bearing Tree signs.

Set a 6 ft. galvanized steel guard post with Land Survey Marker and Property Boundry decals West 5.0 ft. dist. form corner.

Magnetic Declination: 20° East.



Cross Index No

Cor. 2 M.S. 8995 Yellow jacket Lode

27N ^{R.} 31W