


CERTIFIED LAND CORNER RECORDATION  
(REFERENCE FSM 7153.53)

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

Found a 3" iron pipe approximately 30" above ground at corner position.  
Broken tree N66W, 73.1' with tree lying on ground with visible scribing.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED  
TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Set a 2 1/2" X 30" Aluminum pipe with cap marked:  
Date of work: May 1980  
From which: 14" Fir bears N 70 W, 88.4'  
Marked S3 BT  
18" Fir bears N 30 E, 115.9'  
Marked S2 BT  
No other trees available



SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.  
(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

Surveyor's Seal




I, Gary Crismon  
certify that the information shown herein is true and correct.  
Signature of Ground Party Chief

I, Stephen D. Staab  
certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.  
Signature of Surveyor

DIAGRAM OF CORNER:

N. T28N R27W



◆ = Corner recorded on the sheet

5619-S  
Registration Number

Office of Clerk and Recorder, County of Lincoln  
This "corner record" was filed for record on the 4th day of February 1981, was noted on the cross-index plat and is assigned page No. 1000, in book No. 1  
Eleanor L. Vaughn, by Michel Groom, Deputy  
County Official

Cross Index No. E-17 T. 28N R. 27W Mer.