
CERTIFIED CORNER RECORDATION

Corner N 1/16 Secs. 34 & 35 T 28 N. R. 30 W. P.M.M. LINCOLN County

- Record: No previous survey.
- II. Found: No evidence found.
- III. At the corner point Set an iron rebar, 24 ins. long, 5/8 ins. diam., 36 ins. in the ground, with a $3\ 1/4$ ins. diam., aluminum U.S.F.S cap mkd. as shown:



From which:

A fir, 17 ins. diam., bears N45°E, 75.6 ft. dist., mkd. N 1/16 S35 BT. A fir, 11 ins. diam., bears N78°E, 47.9 ft. dist., mkd. N 1/16 S35 BT.


Painted red bands around BT's and attached Bearing Tree and Land Survey Monument signs.

Survey crew: Steve Boyer, Tom Hommel


Magnetic declination: 20° East assumed

Equipment used: Hand compass and loggers tape

U. S. Forest Service, Supervisiors Office, 1101 Hwy. 2 West, Libby, MT. 59923 (406) 293-6211



NOT TO SCALE SKETCH OF CORNER



Lincoln Office of Clerk and Recorder, County of .. This "corner record" was filed for record on . was noted on the cross-index plat and is assigned page No

book No.

corner this sheet

Sec. 34

Cross Index No.

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors