
## CERTIFIED CORNER RECORDATION

Corner 1/4 Secs. 34 & 35 T 28 N. R. 30 W. P.M.M. LINCOLN County

- Record: 1900 original record by Burton S. Adams: 40.00 chains, "Set a fir post 3 ft. long, 6 ins. square, 24 ins. in the ground, for 1/4 sec. cor., marked 1/4 S. 34, on W. face and 35 on E. face. The corner falls in a swamp and pits are impratciable. There are no sutible bering trees within reasonable limits.
- II. Found: No evidence found.
- III. At the corner point The position determined by proportionate distance, set an aluminum post, 30 ins. long, 2 1/2 ins. diam., 46 ins. in the ground, with a 3 1/4 ins. diam., aluminum U.S.F.S cap mkd. as shown:



From which:

An iron rebar, 24 ins. long, 5/8 ins. diam., set 22 ins. in the ground, for a reference monument, bears S0°52'47"W, 852.54 ft. dist., with a 1 1/4 ins. diam., plastic cap mkd. "F.S. CONTROL".

An iron rebar, 24 ins. long, 5/8 ins. diam., set 22 ins. in the ground, for a reference monument, bears S19°08'59"W, 540.10 ft. dist., with a 1 1/4 ins. diam., plastic cap mkd. "F.S. CONTROL".


Set 2, 6 ft. galvanized steel guard posts 1 ft. east and west, with Land Survey Monument decals attached.

Survey crew: Steve Boyer, Tom Hommel

Magnetic declination: 20° East assumed

Equipment used: Hand compass and loggers tape


U. S. Forest Service, Supervisiors Office, 1101 Hwy. 2 West, Libby, MT. 59923 (406) 293



Office of Clerk and Recorder, County of Lincoln	This "corner
was noted on the cross-index plat and is assigned page	10513 in
book No	Cummy Dyeld
Cou	inty Official

Cross Index No. X-17 T. 28N. R. 30W. P.M., MT

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors



MONTANA

ROGER: 0. GREEN

13769LS

corner this sheet