
CERTIFIED CORNER RECORDATION

Corner CS-NW-SW 1/256 S35 T 28 N. R. 30 W. P.M.M. LINCOLN County

- Record: No previous survey.
- II. Found: No evidence found.
- III. At the corner point Set an iron rebar, 24 ins. long, 5/8 ins. diam., 36 ins. in the ground, with a 3 1/4 ins. diam., aluminum U.S.F.S cap mkd. as shown:



From which:

A fir, 12 ins. diam., bears N85°E, 157.6 ft. dist., mkd. CSNWSW 1/256 S35 BT. A fir, 18 ins. diam., bears N48°E, 160.6 ft. dist., mkd. CSNWSW 1/256 S35 BT.


Set a 2, 6 ft. galvanized steel gurard posts 3 ft. north and east with Property Boundary and Land Survey Monument decals attached. Painted red bands around BT's and attached Bearing Tree and Land Survey Monument signs.

Survey crew: Steve Boyer, Tom Hommel

Magnetic declination: 20° East assumed

Equipment used: Hand compass and loggers tape

U. S. Forest Service, Supervisiors Office, 1101 Hwy. 2 West, Libby, MT. 59923 (406)



CERTIFICATION Steven A. Boyer 9750LS Roger O. Green ertify that this Corner Record correctly represents work erformed by me or under my direction in compliance were "Corner Recordation Act" (78-722-101, et seq., M.C. Date: 1/24/2001 Reg. No. 13769LS Employer: U. S. Forest Service

ROGER O GREEN.

13769LS

Office of Clerk and Recorder, County of Lincoln This "corner
was noted on the cross-index plat and is assigned page No. 10518, in book No. Sounty Official
book No.
County Official

Cross Index No. X.75-17.5 T. 28N. R. 30W. P.M., MT · corner this sheet

Sec. 35

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors