
CERTIFIED CORNER RECORDATION

Corner SE-NW-SW 1/256 S35 T 28 N. R. 30 W. P.M.M. LINCOLN County

- I. Record: No previous survey.
- II. Found: No evidence found.
- III. At the corner point
 Set an iron rebar, 24 ins. long, 5/8 ins. diam., 38 ins. in the ground, with a 3 1/4 ins. diam., aluminum U.S.F.S cap mkd. as shown:



From which:

A fir, 10 ins. diam., bears S4°W, 10.9 ft. dist., mkd. SENWSW 1/256 S35 BT. A fir, 19 ins. diam., bears S79°W, 10.5 ft. dist., mkd. SENWSW 1/256 S35 BT.

Set 2, 6 ft. galvanized steel guard posts 3 ft. south and west, with Property Boundary and Land Survey Monument decals attached. Painted red bands around BT's and attached Bearing Tree and Land Survey Monument signs.


Survey crew: Steve Boyer, Tom Hommel


Magnetic declination: 20° East assumed

Equipment used: Hand compass and loggers tape

ROGER O.
GREEN
13769LS
10 SURVE

U. S. Forest Service, Supervisiors Office, 1101 Hwy. 2 West, Libby, MT. 59923 (406) 293 6211







NOT TO SCALE

CERTIFICATION

I, Steven A. Boyer 9750LS

certify the information shown herein is true and correct.

Signature Ground Edrty Chief

I, Roger O. Green

certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70–22-101, et seq., M.C.A.)

Date:1/24/2001 Reg. No. 13769LS

Employer: U. S. Forest Service

Office of Clerk and Recorder, County of Lincoln


This "corner record" was filed for record on 35, 200 /

was noted on the cross-index plat and is assigned page No. 10519, in book No.

County Official

Cross Index No. X.75—17.75 T. 28N. R. 30W. P.M., MT

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors



corner this sheet