
## CERTIFIED CORNER RECORDATION

Corner S-S 1/64 S34 & S35 T 28 N. R. 30 W. P.M.M. LINCOLN County

- I. Record: No previous survey.
- II. Found: No evidence found.
- III. At the corner point

  Set an iron rebar, 24 ins. long, 5/8 ins diam., by 20 in the ground, with a 3 1/4 ins diam., aluminum U.S.F.S cap mkd. as shown:



From which:

A fir, 11 ins. diam., bears N60°E, 6.7 ft. dist., mkd. SS 1/64 S35 BT. A larch, 15 ins. diam., bears N58°W, 12.0 ft. dist., mkd. SS 1/64 S35 BT.

Set 2, 6ft. galvanized steel posts, 3 ft. North and East of the corner, with Property Boundary and Land Survey Monument decals attached. Painted red bands around BT's and attached Bearing Tree and Land Survey Monument signs.

Survey crew: Steve Boyer, Tom Hommel

Magnetic declination: 20° East assumed

Equipment used: Hand compass and loggers tape

U. S. Forest Service, Supervisiors Office, 1101 Hwy. 2 West, Libby, MT. 59923 (406) 293-6211



CERTIFICATION

ROGER O. GREEN.

3769LS

Steven A. Boyer 9750LS ortify the information shown herein is true and correct

Signature Ground Party Chief

Roger O. Green

certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70722-101, et seq., M.C.A.)

Mogh D. Ham.

Algunture of Surveyor & Seal

Date:<u>1/24/2001</u> Reg. No. <u>13769LS</u>

Employer: U. S. Forest Service

N58'W N60'E 6.7ft.

SKETCH OF CORNER


No Scale

Office of Clerk and Recorder, County of Lincoln This "corner record" was filed for record on 35, 200/
was noted on the cross-index plot and is assigned page No. 10522, in book No.

County Official County Official

Cross Index No.  $\underline{Y.5}$  -  $\underline{17}$  T.  $\underline{28N.}$  R.  $\underline{30W.}$  P.M., MT

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors



· corner this sheet