

INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner W 1/16 Corner Section 4, 9 T. 28 N R. 33 W P.M.M. Lincoln County

I. 1986 Davis Surveying, Inc.

I set a U.S.D.A. aluminum cap & pipe, 3 1/4 inch. dia. x 30 inch long marked:

from which:

A cedar 30 inch DBH, bears N 5° W 17.4 feet from center of tree
Scribed W 1/16 S 4 BT.

Set an aluminum post to the east of corner.

Post marked with survey marker sign # LSM-130.


Painted a red bank, 6 inch wide around BT's with a BT sign on front and
warning sign # 54.9 on back.

Trees are notched at root crowns.

Rock pile around corner.

from which:

A cedar 10 inch DBH, bears N 85° W 18.9 feet from center of tree scribed
W1/16 S 4 BT.



NOT TO SCALE

SKETCH OF CORNER

CERTIFICATION

I, Janet St. Sigel
certify the information shown herein is true and correct.

Janet St. Sigel
Signature of Ground Party Chief

I, David Davis
certify that this corner record correctly represents work performed
by me or under my direction in compliance with the "Corner
Recordation Act," (MCA, 70-2-101, et seq.) (M.D.A. 1)

David Davis
Signature of Surveyor & Seal

Date: Sept 19, 1984

Employer: Davis Surveying Inc

Office of Clerk and Recorder, County of Lincoln. This "corner
record" was filed for record on the 17th day of 1984
was noted on the cross-index plat and is assigned page No. 3435 in
book No. _____

Janet St. Sigel by Deed Sigel
County Official Deputy

Sec.	