## CERTIFIED CORNER RECORDATION


CORNER N1/4 CORNER SEC. 14 T. 29N , R. 26W , P.M.M., LINCOLN COUNTY

FOUND: 3 1/4" ALUM CAP STAMPED AS SHOWN, FROM WHICH;.

FIRE HAS DESTROYED ALL BEARING TREE EVIDENCE A 6 FOOT STEEL POST 3 FEET EAST AND A 6 FOOT STEEL POST 3 FEET WEST

MAINTENANCE: REMOVED BRUSH AND TREE LIMBS FROM CORNER AREA.

STEEL POST - STEEL POST



SKETCH OF CORNER

CERTIFICATION

I, DAN CROFT

CERTIFIY THE INFORMATION SHOWN HEREIN IS TRUE AND CORRECT.

SIGNATURE GROUND PARTY CHIEF

I, MARC J. CARSTENS

CERTIFIY THAT THIS CORNER RECORD CORRECTLY REPRESENTS WORK
PERFORMED BY ME OR UNDER MY DIRECTION IN COMLIANCE WITH THE

"CORNER RECORDATION ACT" (70-22-101, ET SEQ., M.C.A.)

SIGNATURE OF SURVEYOR & SEAL

5-10-2014

DATE

CARSTENS SURVEYING
EMPLOYER

MARC J.
CARSTENS
5940LS

SURVE

• CORNER THIS SHEET

SEC.\_14