


CERTIFIED CORNER RECORDATION

Corner 1/4 Sec. 18 T. 29N R. 26W P.M., MT Lincoln County

I. 1932 B.L.M. Resurvey of the Horse Plains Guide Meridian by Fred L. Cumming et al.: Point for 1/4 sec. cor. of secs. 18, as hereafter determined. Set an iron post, 3 ins. long, 1 in. in diam., 28 ins. in the ground, for 1/4 sec. cor. for sec.18, with the brass cap mkd. as shown:



Established two bearing trees:

- A larch, 6 ins. diam., bears N84°E, 12 lks. dist., mkd. "1/4 S18 BT".
- A larch, 7 ins. diam., bears S60°E, 22 lks. dist., mkd. "1/4 S18 BT".

II. Found a 1 in. diam. iron pipe, protruding 1.4 ft. above the ground, firmly set, with a 2 1/2 in. diam. brass cap, mkd. as shown above. No bearing trees found.


III. No suitable trees within limits, therefore, from the corner point, I set two posts:

- A 6 ft. steel guard post, bears North, on property line, 10.0 ft. dist.
- A 6 ft. steel guard post, bears South, on property line, 2.95 ft. dist.

Attached Land Survey Monument and Property Boundary decals to the guard posts.



Magnetic Declination: 20° East.



SKETCH OF CORNER

CERTIFICATION

I, Rex O. Rice
certify the information shown herein is true and correct.

I, Ronald A. Pearson
certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.C.A.)

Ronald A. Pearson
 Signature of Surveyor & Seal

Date: 12/30/96

Reg. No.: 9008LS

Employer: U.S. FOREST SERVICE

Office of Clerk and Recorder, County of LINCOLN. This "corner record" was filed for record on FEB 3, 1997 was noted on the cross-index plat and is assigned page No. 9056, in book No. _____ CORAL M. CUMMINGS County Official *CJ JB*

