
•	CERTIFIED CORNER RECORDATION
Corner _	N 1/16 S5 29 N 27 W Lincoln o
I. Rec	ord: None
II. For	und: No monuments found during area search.
III. <u>P</u> e	repetuation: At the corner point, determined by survey, set a 5/8 ins. diam. steel rebar 24 ins. long 22 ins. in the ground, with a 3 1/4 ins. diam. Aluminum cap marked as shown below from which:
	A fir, 6 ins. diam., bears N. 46° E., 23.22 ft. dist., scribed N 1/16 S4 BT. A fir, 4 ins. diam., bears S. 80° W., 19.23 ft. dist., scribed N 1/16 S5 BT.
	Painted faces and 6 in. wide red bands to all bearing trees and attached Land Survey Monument and Bearing Tree signs.
	Set a steel post on line 6 ft. West of set monument with Survey Monument and Property line stickers attached.
	Magnetic declination: 18° East
	Equipment used: Hand compass and loggers tape
	T29N R27W
	(N 1/16)
	\ S5 S4 /
	7322 LS
	2006
•	
Koota	enai Surveyors Inc., 314 California Av., Libby, MT. 59923 (406) 293—4354
<u></u>	CERTIFICATION
demption F	IIII - PCIC Kelly Rooney



Office of Clerk and Recorder, County of Lincoln This "corner 200821 BOOK: CCR CCGR'S PAGE: 11022 Pages: 1

STATE OF MONTANA LINCOLN COUNTY

was noted on the crossbook No.

FEE: \$0.00
To: FILED ,

Cross Index No. B 09 T. 29N R. 27W P.M., MT

Sec. 5

- corner this sheet

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors
in-shared\Corner Rec\Cross Wolf PCTC.dwg, 1/2/2007 12:29:46 PM, Konka