CERTIFIED CORNER RECORDATION Corner E 1/16 S5 T 29 N. R. 27 W. P.M.M. Lincoln County I. Record: None II. Found: No monuments found during area search. III. Perpetuation: At the corner point, determined by survey, set a 5/8 ins. diam. steel rebar 24 ins. long 22 ins. in the ground, with a 3 1/4 ins. diam. Aluminum cap marked as shown below from which:

A fir, 10 ins. diam., bears S. 10° E., 22.24 ft. dist., scribed E 1/16 S5 BT. A fir, 5 ins. diam., bears S. 41° E., 33.67 ft. dist., scribed E 1/16 S5 BT.

Painted faces and 6 in. wide red bands to all bearing trees and attached Land Survey Monument and Bearing Tree signs.

Set a steel post on line 3 ft. East of set monument with Survey Monument and Property line stickers attached.

Magnetic declination: 18' East

Equipment used: Hand compass and loggers tape

T30N R27W

E 1/16 S 5


T29N R27W

7322 LS

2006

Kootenai Surveyors Inc., 314 California Av., Libby, MT. 59923 (406) 293-4354

Redemption Hill - PCTC	57 Fir 10" Fir SKETCH OF CORNER		CERTIFICATION Kelly Rooney certify the information shown herein is true and correct. Signature Ground Party Chief Alvah F. Hughes certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et. seq., M.C.A.) Signature of Suveyor & Spall Date: 10/31/2006 Reg. No. 7322-152
Office of Clerk and Re	Lincoln	This "cor	TERES



Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors