

**CERTIFIED LAND CORNER RECORDATION**  
(REFERENCE FSH 5681.65)


DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

The original corner stone is lost, found the BT's as follows:  
Sec. 12 BT, green Ponderosa Pine, 30" dbh, w/scribing  
Sec. 13 BT, green Ponderosa Pine, 24" dbh, w/scribing

Original record as follows: Slate stone, 14x10x5, 9" in ground  
mkd CC on west, w/4 notches on S & 2 notches on N, from which a  
Pine, 30", N 24°W, 75 lks  
Pine, 20", S 47°W, 87 lks.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED  
TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: 11/20/69



Set a 2" x 30" pipe two feet deep with brass cap at exact  
GLO distances from the original bearing trees listed  
above. Erected a mound of stone around the pipe.  
Notched the base of each BT; painted red around the  
scribed blaze; added BLM - BT tags. Brass Cap stamped  
as shown at left.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.  
(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

Surveyor's Seal


I, .....  
certify that the information shown herein is true and  
correct.

Signature of Ground Party Chief

I, Robert F. Burdick  
certify that I have carefully performed or reviewed the  
work done on the diagrammed corner as reported on this  
recording form and approve the same.

Robert F. Burdick  
Signature of Surveyor

DIAGRAM OF CORNER:



149S  
Registration Number

Office of Clerk and Recorder, County of Lincoln

This "corner record" was filed for record on the 19th day of January 1970, was noted on the cross-index plat and is  
assigned page No. 164, in book No. 1 ELEANOR L. VAUGHN, By: Max Watson Deputy.  
County Official

Cross Index No. J-25 T. 29 R. 28 Mer. 27  
J-1 29 27