INSTRUCTIONS

- 1. Original and/or subsequent record used to evaluate the corner position.
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- 3. Description of monument and accessories set to perpetuate the corner position
- Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
- 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

1/4 Cor. of Secs. 22 & 23 Lincoln Corner_ County

1903 original G.L.O. record by George A. Fessenden and Ranney Y. Lyman: "Set a sandstone, 14 imes 8 imes 6 ins., 9 ins. in the ground, for 1/4 sec. cor., marked 1/4 on W. face, from which

A tamarack, 30 ins. dia., bears N13 $^{\circ}$ 30'E, 15 lks. dist., marked 1/4 S23 BT. A tamarack, 24 ins. dia., bears $N57^{\circ}30$ W, 28 lks. dist., marked 1/4 S22 BT.

1963 remonumentation, Corner Search Card record by Norman Berg, Reg. #1963S: "Calculated coordinates and located sandstone as described, and stumps of bearing trees with correct bearings and distances from said stone."

> T29N R28W 22 23 1/4 NB 1963s

"Placed stone in 3 ft. hole, planted a pipe with brass cap over stone."

Blazed two trees:

- A fir, 8 ins. dia., bears N42 E, 20.71 ft. dist., mkd. FSRM.
- A tamarack, 30 ins. dia., bears N48 $^{\circ}$ W, 32.7 ft. dist., mkd. FSRM.
- II. Found a 2 ins. dia. pipe, 10 ins. above ground with a brass cap marked as shown above, from which
 - A douglas fir, 14 ins. dia., bears N42 E, 21.2 ft. dist., overgrown blaze.
 - A larch, 27 ins. dia., bears N48 W, 33.6 ft. mkd. FSRM.

 - A rotten stump, bears N13 $^{\circ}$ E, 10.3 ft. (15.6 lks.) dist. (original) A rotten stump, bears N57 $^{\circ}$ W, 18.5 ft. (28.0 lks.) dist. (original)
- III. Painted a red band around each bearing tree and attached Land Survey Monument and Bearing Tree signs. Set a 6 ft. galvanized steel guard post with Survey Marker decal attached, 3 ft. South from corner. Magnetic Declination: 20° East.

14" FIR

CERTIFICATION

Kevin Todd

certify the information shown herein is true and correct.

Alvah F. Hughes certify that this Corner Record correctly

12/21/90 Reg. No.

Employer: U.S. FOREST SERVICE

SKETCH OF CORNER

Sec. Office of Clerk and Recorder, County of _ . This "corner was noted on the cross-index plat and is assigned page No. _ book No. -

Cross Index No. .

· - corner this sheet